

## How to dismount the PM-11 Datalogger from the Heavy-duty cabinet and to prepare installation on a tripod.

1. Disconnect two power cables from the battery's contacts (if they are connected).
2. Disconnect all cables and plugs connected to the PM-11 Datalogger (power cable, RTH cable, sensors, RS485 cable, if present, etc.)
3. Unscrew four bolts, two above and two below the PM-11, as shown in Photo 1. Remove the PM-11 with the back panel from the Heavy-duty cabinet.
4. Dismount two fixing brackets, as shown in Photo 2, and attach them to the PM-11 back panel as shown in Photo 3. The PM-11 is ready for mounting on a tripod.



Photo 1



Photo 2



Photo 3